

INSTALLATION GUIDELINE

UNIVERSAL COVER TF

FOR DEW POINT SENSOR TF 3 G/M-22 AND TF 3 P/R-22



MOUNTING WITHOUT DRILLING OR GLUING



The **universal cover TF** should only be fitted after all ceiling work has been completed.



First guide the "sensor tubes" of the dew point sensor through the two large openings in the base plate. The smooth side of the base plate should face the ceiling.



To fix the base plate, put the two silicone rings on the "sensor tubes" and push them all the way up. The base plate should now hang firmly on the ceiling.

INSTALLATION GUIDELINE
UNIVERSAL COVER TF
FOR DEW POINT SENSOR TF 3 G/M-22 AND TF 3 P/R-22



MOUNTING WITHOUT DRILLING OR GLUING



Cut off the two ends of the "sensor tubes" so that they are no longer than 10 mm from the base plate.



Finally, place the cover on the base plate until it clicks into place.